

THE ENFIELD CYCLE COMPANY LIMITED

HEAD OFFICE & WORKS: REDDITCH

ROYAL ENFIELD SERVICE BULLETIN No:

39

Date: 11.6.59

CONSTELLATION TAPPET SETTING.

Experience has shewn that whilst the settings given in the Instruction Book and Workshop Manual are satisfactory for normal use, the exhaust tappet clearance must be increased for hard driving, and we recommend .005" clearance when cold for sustained high speed work.

ELECTRIC HORN SHORTING ON FRAME

On machines having the horn mounted on the front engine plate bolt, it can happen that if the horn is loose and swivels forward, the terminal contacts the frame down tube and causes a dead short with burnt out harness. If, as is customary, the front terminal is the live one, reverse the leads, so that if contact is made the horn blows. This is a safeguard and a warning.